

STEP 1. Tools needed: Screwdriver and lighter

STEP 2. Fold the EFT at point of puncture and wrap the EFT around a screwdriver.

STEP 3. Heat the punctured area with a cigarette lighter being careful to keep the flame at least 4 cm away from the EFT. Heat the EFT for about 20 seconds while slowly moving the flame around the area of the tear. Allow EFT to cool for about 1 minute to ensure a good repair.

STEP 4. For safety reasons, repairs should be made in a 1m area clear of combustible materials.

Important Notes :

- Stop heating the tube immediately if white smoke appears.
- Do not touch the flame directly to the tube.
- Please do not repair EFT in forests or grasslands.

